**Characteristics** Thermoplastic Hot Melt adhesive, 100% solids content.

Low odor ,good bonding

Features

Properties	Specs	Testing Methods
Base	Syntheitc　Rubber Copolymers	
Shape	Block or Pillow	Observation
Color	White	Observation
Softening Point	85±5	ASTM-E28（R&B）
Viscosity		Brookfield Viscometer RVDV Spindle #27

Viscosity curve

Instruction For Use 1.Operation Temperature：140℃.

2. Application methods: Spray、Slot.

Notice 1.Do not touch the molten adhesive. In case of burns from hot adhesive, immediately flush skin

with cold water and cover with a clean dressing, do not remove adhesive. Have burn treated by

a physician.

2.All surfaces should be clean and free of loose elements.

3.Do not heat the adhesive over 180℃ in prolonged time to avoid material decomposition and

consequent decreased properties.

4. Please store hotmelt glue in well-ventilated place, away from direct sunshine.

Note Product color may vary due to different raw material batch. This variation does not impact on product

properties.

Retention time：5 years

C&M Filtration Solutions Co.,Ltd.

13JKaikaiPlaza,No888,Wanhangdu

Rd,Shanghai,China

Tel:+86-21-62030560

www.cmfiltration.com